



**James Campbell Company, LLC**  
**1001 Kamokila Boulevard**  
**Kapolei, Hawaii 96707**

**2016 Institutional Controls Annual Report**  
**Del Monte Pineapple Plantation Superfund Site**  
**Kunia, Oahu, Hawaii**

September 14, 2016



---

Chad Kaiwikuamoo  
Project Engineer

**2016 Institutional Controls  
Annual Report**

Del Monte Pineapple Plantation  
Superfund Site  
Kunia, Oahu, Hawaii

Prepared for:  
James Campbell Company, LLC

Prepared by:  
Arcadis U.S., Inc.  
1003 Bishop Street  
Suite 2000  
Honolulu, Hawaii 96813  
Tel 808.522.0321  
Fax 808.522.0366

Our Ref.:  
HI011093.0006  
Date:  
September 14, 2016

*This document is intended only for the use of the individual or entity for which it was prepared and may contain information that is privileged, confidential and exempt from disclosure under applicable law. Any dissemination, distribution or copying of this document is strictly prohibited.*

## Table of Contents

<b>1. Introduction</b>	<b>1</b>
<b>2. Project Objectives</b>	<b>1</b>
<b>3. Monitoring of Institutional Controls</b>	<b>1</b>
3.1 Conveyance of Property Titles	2
3.2 Status of Remaining Property	2
3.3 Certifications of Compliance	2
3.4 Records Review	3
3.5 Site Inspection	3
<b>4. Summary and Conclusions</b>	<b>5</b>
<b>5. References</b>	<b>6</b>

### Figures

Figure 1	Site Vicinity Map
Figure 2	Site Plan
Figure 3	Site Plan and Kunia Village
Figure 4	Site Plan and Section 7 and 9
Figure 5	Site Plan and Section 2
Figure 6	Site Plan and Section 6
Figure 7	Site Plan and Section 8
Figure 8	Well Restriction Area and DLNR Well Number Quadrants

### Appendices

A	Source Area Boundary and Land Court Map
B	Lessee Certifications of Compliance

## **1. Introduction**

Arcadis U.S., Inc. (Arcadis) has prepared this Institutional Controls Annual Report (IC Annual Report) on behalf of the James Campbell Company LLC (Campbell) to comply with the requirements of the March 19, 2007 Institutional Controls Consent Decree (Consent Decree) for the Del Monte Pineapple Kunia Plantation Superfund Site. Campbell owned the Site at the time of the Consent Decree, but no longer owns any portion of the Site. A Site Vicinity Map is presented as Figure 1 and a Site Plan is presented as Figure 2. The U.S. Environmental Protection Agency (EPA) identification number for the Site is HID 980637631.

## **2. Project Objectives**

The Consent Decree requires that Campbell monitor institutional controls at the Site to verify that property owners and lessees have not:

1. undertaken any construction in the Source Area or the Well Restriction Area that has damaged or interfered with, or might damage or interfere with, any basal groundwater monitoring or extraction wells, or equipment associated with those wells; or
2. submitted an application for a water-use permit to withdraw water from any well located in the Well Restriction Area.

The objectives of this report are to summarize activities undertaken by Campbell during the previous year to comply with the requirements of the Consent Decree and to certify such information as required by the EPA. This report is for the period September 18, 2015 to September 17, 2016.

## **3. Monitoring of Institutional Controls**

To comply with the Consent Decree, Arcadis obtained records from Campbell associated with Paragraph 7 of the Consent Decree which requires that Campbell provide the EPA with written notice before completing a proposed title conveyance of property within the Site. Additionally, Arcadis performed monthly reviews of State of Hawaii Department of Land and Natural Resources (DLNR) Water Commission Monthly Reports and performed a site visit to verify that required institutional controls were in place. This information is summarized in the following sections.



### 3.1 Conveyance of Property Titles

No conveyance of property titles occurred during this past year. However, in September 2010, Army Hawaii Family Housing LLC changed its name to Island Palm Communities LLC.

Although Campbell no longer retains ownership of any portion of the Site, they will continue to monitor property transactions and provide appropriate notifications to future property owners and the EPA as required by the Consent Decree.

### 3.2 Status of Remaining Property

The Source Area was conveyed to Hawaii Agriculture Research Center on November 17, 2009 as part of the Kunia Village disposition. Subdivision of the Source Area has been authorized and approved by the Land Court, State of Hawaii (Land Court Application 1069). The Source Area boundary and final Land Court Map are shown in the figures presented as Appendix A.

### 3.3 Certifications of Compliance

Certifications of compliance with the Declaration of Environmental Restrictions (Well Restriction Area) from current property owners for the past year are summarized in the table below. Copies of signed certifications are presented in Appendix B.

Purchaser	Site Section	Certification Date	Signatory
Hawaii Agriculture Research Center	Kunia Village (Figure 3)	July 6, 2016	Stephanie Whalen
Island Palm Communities LLC (formerly known as Army Hawaii Family Housing LLC)	Sections 7 and 9 (Figure 4)	July 11, 2016	Pete Sims
Kunia Loa Ridge Farmlands	Section 2 (Figure 5)	July 12, 2016	D.L. Garwood
Syngenta Hawaii, LLC	Section 6 (Figure 6)	July 26, 2016	Steven Kai
Fat Law's Farm, Inc.	Section 8 (Figure 7)	July 27, 2016	Tim Law

### **3.4 Records Review**

Arcadis reviewed Monthly Water Resource Bulletins from the DLNR Commission on Water Resource Management (the Commission) to verify that no new applications for well construction and pump installations or groundwater use permits within the Well Restriction Area had been submitted during the previous year. The Well Restriction Area covers portions of DLNR well quadrants 3-2503, 3-2603 and 3-2703 as shown in Figure 8. Review of the bulletins (September 2015 through August 2016) indicated that no new well or groundwater permit applications were submitted to the DLNR for these three quadrants during this reporting period. The bulletins can be found at [www.hawaii.gov/dlnr/cwrm](http://www.hawaii.gov/dlnr/cwrm).

Arcadis also reviewed publicly available minutes from Commission meetings (September 2015 through August 2016) to verify that no water use permits for the Well Restriction Area were submitted to the DLNR during this reporting period. The meeting minutes can be found at [www.hawaii.gov/dlnr/cwrm](http://www.hawaii.gov/dlnr/cwrm).

The 2013 IC Annual Report indicates that permit applications were previously submitted for a new well (identified as well number 3-2402-006) to be located approximately 1,500 feet southeast of the Well Restriction Area boundary. According to the August 15, 2012 Commission meeting minutes, the "new water use permit would provide back-up irrigation water for 2,052 net acres of seed corn and various other crops, currently irrigated by surface water from the Waiahole Ditch System." However, in order to effectively prevent "providing a water user with two allocations of water in the same land use," the following recommendation was made: deny the groundwater use permit application; allow construction of the well; and approve installation of the pump and pump testing. During subsequent Commission meetings, additional recommendations were made (i.e., requiring the applicant to submit an Emergency Plan addressing potential failures to the Waiahole water system). Ultimately, based on the December 19, 2012 Commission meeting minutes, the "motion to approve the application failed for lack of a majority."

### **3.5 Site Inspection**

On August 3, 2016, Arcadis conducted a visual inspection of the Source Area, the Phytoremediation Area and Basal Monitoring Wells (BMW). The major components of the remediation system consist of:

- A soil vapor extraction (SVE) system with carbon absorption to remove deep soil contaminants and reduce perched water impacts on the basal aquifer.
- Vegetated soil cover and storm water controls uphill of the Source Area.

- A groundwater extraction system providing hydraulic containment and dewatering of the perched aquifer area. Extracted groundwater is treated using phytoremediation.

The Source Area contains: BMW-1 and BMW-2, monitoring wells, storm water controls, and SVE and groundwater extraction systems consisting of extraction wells, treatment system components, and controls. The SVE controls are installed on a concrete slab enclosed by a chain link fence and metal roof. In general, all wells and remediation components located inside of the Source Area appeared to be in good condition. Arcadis did, however, observe the following:

- Several of the stand-alone monitoring wells and piping displayed evidence of surface corrosion. Each well within the Source Area contained what appeared to be a functioning lock.
- Excessive paint chipping was observed on several protective bollards surrounding the stand-alone monitoring wells.
- Several monitoring wells were observed to have faded or incomplete well identification numbers.
- Although likely not structurally significant, surface cracks were detected on numerous concrete pads throughout the Source Area.
- Surface rust staining was observed circling the base of the aboveground water storage tank located adjacent to the SVE control area.
- Pipe and hose connections of the SVE equipment previously contained rudimentary wraps consisting of duct tape and absorbent material used to prevent potential slow leaks. These wraps are still present.
- Minor staining was observed beneath the SVE equipment in the controls area and water (most likely condensation) was observed on the floor adjacent to a compressor on the north side of SVE controls area.
- BMW-1 is missing bollards around the perimeter of the concrete slab.
- An electrical box attached to an individual bollard surrounding BMW-2 displayed evidence of corrosion and was unsecured.
- An airline located near the southeast corner of SVE controls area appeared to have a slight leak.

During the inspection, the Source Area landscape appeared maintained. Vegetation (grasses consistent with the surrounding agricultural areas) seemed healthy, along with a few patches of exposed soil. The drainage channel located in the northeastern portion and eastern boundary of the Site was heavily

vegetated and the diversion ditch south of the SVE controls area was observed to be in good condition with minimal vegetation.

The Phytoremediation Area appeared to be in good condition. Previously damaged areas of the high-density polyethylene (HDPE) liner have been repaired. Arcadis made the following observations: a former utility pole was lying adjacent to the southeast edge of phytoremediation liner; several tree limbs had fallen near the entrance to Phytoremediation Area; and a well along the northern edge of the phytoremediation liner was missing a cap (the cap was laying on the ground near the well).

After examining the Phytoremediation Area, Arcadis conducted a drive-through inspection of the basal monitoring well field including wells BMW-3 through BMW-7, and the DLNR Mauka Deep Monitoring Well. The wells appeared intact and secure. Arcadis observed the following:

- Well monument covers on the DLNR Mauka Deep Monitoring Well displayed evidence of corrosion. Two locks were present on well cover; but only one was locked. There were no locks on the fenced enclosures surrounding the well.
- Paint has chipped from the bollards surrounding wells BMW-3 through BMW-7. Minor corrosion was observed on chipped areas of the bollards.

Arcadis was unable to inspect the Pearl Harbor Middle Deep Exploratory Well due to heavy vegetation that made the well inaccessible.

#### **4. Summary and Conclusions**

Arcadis conducted an inspection to verify that institutional controls were working effectively in the Source Area and Well Restriction Area of the Site. Based on our review of available information, Arcadis concluded the following:

- Affected lessees and landowners certified compliance with the Consent Decree;
- No permits for water use in restricted areas have been requested of the DLNR's Water Commission;
- An inspection of the Source Area, the Phytoremediation Area and basal monitoring wells confirmed that the remediation system is intact and operational; and
- No construction or other activities have interfered with the functioning of the basal monitoring wells.

## **5. References**

Golder Associates, Inc. (Golder). 2007. Perched Groundwater Remedial Design Report for the Del Monte Corporation (Oahu Plantation) Superfund Site. December 20.

Environmental Protection Agency, Region IX. 2007. CERCLA Administrative Order on Consent with the James Campbell Company, LLC. March 19.

## Figures






0 1 2 3 4 5 6 7 miles  
0 1 2 3 4 5 6 7 10 km  
Map created with TOPO!® ©2002 National Geographic (www.nationalgeographic.com/topo)






Site Vicinity Map

Del Monte/Kunia





#### EXPLANATION


-  Well Locations
-  EPA Well Restriction Area
-  Source Area

Source: Letter to Ms. Janet Rosati, EPA Project Coordinator from James Campbell Company, October 2, 2007




#### Site Plan

Del Monte/Kunia





#### EXPLANATION

-  EPA Well Restriction Area
-  Source Area
-  Kunia Village

Source: Letter to Ms. Janet Rosati, EPA Project Coordinator from James Campbell Company, October 2, 2007


#### Site Plan and Kunia Village

Del Monte/Kunia

 **ARCADIS** Design & Consultancy  
for natural and built assets

Figure 3





#### EXPLANATION

- EPA Well Restriction Area
- Source Area

#### Site Plan and Sections 7 and 9


Del Monte/Kunia

Source: Letter to Ms. Janet Rosati, EPA Project Coordinator  
from James Campbell Company, December 3, 2008

**ARCADIS** Design & Consultancy  
for natural and  
built assets

Figure 4





#### LEGEND

- Well Locations
- Del Monte Site Boundary
- Land Court Lots

0' 4,000'  
Scale: 1"=4,000 Feet



Section 2

#### SECTION 2

**Del Monte Corporation  
(Oahu Plantation) Superfund Site**

#### EXPLANATION

- EPA Well Restriction Area
- Source Area

Site Plan  
and Section 2


Del Monte/Kunia

Source: Letter to Ms. Janet Rosati, EPA Project Coordinator  
from James Campbell Company, September 15, 2008

**ARCADIS** Design & Consultancy  
for natural and built assets

Figure 5





#### EXPLANATION


- EPA Well Restriction Area
- Source Area

Source: Letter to Ms. Janet Rosati, EPA Project Coordinator  
from James Campbell Company, September 15, 2008

#### Site Plan and Section 6

Del Monte/Kunia





#### EXPLANATION

- EPA Well Restriction Area
- Source Area

#### Site Plan and Section 8


Del Monte/Kunia

Source: Letter to Ms. Janet Rosati, EPA Project Coordinator  
from James Campbell Company, October 2, 2007

**ARCADIS** Design & Consultancy  
for natural and built assets

Figure 7





#### EXPLANATION



EPA Well Restriction Area


#### Well Restriction Area and DLNR Well Number Quadrants

Del Monte/Kunia

## **Appendix A**

Source Area Boundary  
and Land Court Map

SUBDIVISION OF LOT 17847  
AS SHOWN ON MAP 1370  
INTO LOTS 17847-A AND 17847-B  
AT HONOLULU, EWA, OAHU, HAWAII



**R. M. Towill Corporation**

2024 N. King Street, Suite 200  
Honolulu, Hawaii 96819  
August 23, 2011

Don L.M. Aikta      4/30/12  
Expiration Date  
Licensed Professional Land Surveyor  
Certificate Number 12749  
Land Court Certificate Number 312

OWNER: HAWAII AGRICULTURE RESEARCH CENTER  
TRANSFER CERTIFICATE OF TITLE: 964,710  
OWNER: KUNIA VILLAGE TITLE HOLDING CORPORATION  
TRANSFER CERTIFICATES OF TITLE: 1,056,407 ET AL


AUTHORIZED AND APPROVED BY ORDER OF THE JUDGE  
OF THE LAND COURT DATED APRIL 18, 2012  
BY ORDER OF THE COURT.

*Kaileen Harawane*  
REGISTRAR OF THE LAND COURT

filed January 24, 2012  
Janice L. Brown,  
clerk



TRUE NORTH  
SCALE 1 IN. = 200 FT.



**PROPOSED SOURCE AREA  
KUNIA WELLS  
AT HONOULIULI, EWA, OAHU, HAWAII**

## **Appendix B**

### **Lessee Certifications of Compliance**

**CERTIFICATION OF COMPLIANCE WITH DECLARATION OF  
ENVIRONMENTAL RESTRICTIONS (WELL RESTRICTION AREA)**

I am authorized to make this certification on behalf of the owner(s) of the property described below ("**Property**").

On behalf of said owner(s), I hereby certify, to the best of my and said owner(s)' information and belief, that the following is true and correct as of the date set forth below:

- No application for a water use permit to withdraw water from any well located or to be located in the area shown on the map attached hereto ("**Well Restriction Area**") has been filed by any owner, lessee, licensee, or other occupant or user of the Property (collectively "**Occupant**").

- No Occupant of the Property has undertaken any construction in the Well Restriction Area that has damaged or interfered with, or might damage or interfere with, any basal groundwater monitoring or extraction wells, or equipment associated with those wells.

Date:

7/6/2016

Signature:

Stephanie A. Whalen

Printed Name:

STEPHANIE A. WHALEN

Title:

Executive Director

Property description:

**KUNIA VILLAGE:**

**PARCEL ONE:**

All of that certain parcel of land situate at Honouliuli, District of Ewa, City and County of Honolulu, Island of Oahu, State of Hawaii, more particularly described as follows:

**LOT 17847-A** (area 8.126 acres), as shown on Map 1559, filed in the Office of the Assistant Registrar of the Land Court to the State of Hawaii with Land Court Application No. 1069 of the Trustees under the Will and of the Estate of James Campbell, Deceased.

**BEING** all of the land described in and covered by **Certificate of Title No. 1,098,652.**


**PARCEL TWO:**

All of that certain parcel of land situate at Honouliuli, District of Ewa, City and County of Honolulu, Island of Oahu, State of Hawaii, more particularly described as follows:

**LOT 17847-B** (area 110.960 acres), as shown on Map 1559, filed in the Office of the Assistant Registrar of the Land Court to the State of Hawaii with Land Court Application No. 1069 of the Trustees under the Will and of the Estate of James Campbell, Deceased.

**BEING** all of the land described in and covered by **Certificate of Title Nos. 1,098,653 and 1,098,654.**

End of Property Description





**CERTIFICATION OF COMPLIANCE WITH DECLARATION OF  
ENVIRONMENTAL RESTRICTIONS (WELL RESTRICTION AREA)**

I am authorized to make this certification on behalf of the owner(s) of the property described below ("**Property**").

On behalf of said owner(s), I hereby certify, to the best of my and said owner(s)' information and belief, that the following is true and correct as of the date set forth below:


- No application for a water use permit to withdraw water from any well located or to be located in the area shown on the map attached hereto ("**Well Restriction Area**") has been filed by any owner, lessee, licensee, or other occupant or user of the Property (collectively "**Occupant**").

- No Occupant of the Property has undertaken any construction in the Well Restriction Area that has damaged or interfered with, or might damage or interfere with, any basal groundwater monitoring or extraction wells, or equipment associated with those wells.

Date:

7/11/16

Signature:



Printed Name:

Pete Sims

Title:

Senior Vice President

Property description:

**KUNIA SECTION 9:**

**PARCEL ONE:**

All of that certain parcel of land situate at Honouliuli, District of Ewa, City and County of Honolulu, Island of Oahu, State of Hawaii, more particularly described as follows:

**LOT 17846** (area 2,395.961 acres), as shown on Map 1370, filed in the Office of the Assistant Registrar of the Land Court to the State of Hawaii with Land Court Application No. 1069 of the Trustees under the Will and of the Estate of James Campbell, Deceased.

**BEING** all of the land described in and covered by **Certificate of Title No. 930,578** issued to Army Hawaii Family Housing LLC, a Delaware limited liability company.

End of Parcel One Description



**PARCEL TWO:**

All of that certain parcel of land situate at Hoaeae, District of Ewa, City and County of Honolulu, Island of Oahu, State of Hawaii, more particularly described as follows:

**ROYAL PATENT NUMBER 4490, LAND COMMISSION AWARD 10,474, APANA 9 TO NAMAUU**, situate, lying and being on the westerly side of Kunia Road, being PARCEL 5, and thus bounded and described as per survey dated August 8, 1988:


Beginning at the north corner of this parcel of land and on the westerly side of Kunia Road, the coordinates of said point being referred to Government Survey Triangulation Station "KAPUAI NEW," being 22,750.96 feet North and 4,331.52 feet East, thence running by azimuths measured clockwise from true South:

1. Along the westerly side of Kunia Road, on a curve to the left with a radius of 2,894.90 feet, the azimuth and distance of the chord being:  
  
345° 29' 57" 611.81 feet;
2. 159° 26' 573.67 feet Along Lot M-1-A-1 of Land Court Application 1069;
3. 221° 12' 30" 73.38 feet Along Lot M-1-A-1 of Land Court Application 1069 to the point of beginning and containing an area of 11,930, square feet, more or less.

**BEING** a portion of the premises acquired by Limited Warranty Deed with Covenants and Reservation of Rights December 10, 2008, made by James Campbell Company LLC, as grantor, and Army Hawaii Family Housing LLC, as grantee, filed in the Office of the Assistant Registrar of the Land Court of the State of Hawaii as Document No. 3812212 and recorded in the Bureau of Conveyances of the State of Hawaii as Document No. 2008-185856.

End of Parcel Two







**CERTIFICATION OF COMPLIANCE WITH DECLARATION OF  
ENVIRONMENTAL RESTRICTIONS (WELL RESTRICTION AREA)**

I am authorized to make this certification on behalf of the owner(s) of the property described below ("**Property**").

On behalf of said owner(s), I hereby certify, to the best of my and said owner(s)' information and belief, that the following is true and correct as of the date set forth below:


- No application for a water use permit to withdraw water from any well located or to be located in the area shown on the map attached hereto ("**Well Restriction Area**") has been filed by any owner, lessee, licensee, or other occupant or user of the Property (collectively "**Occupant**").

- No Occupant of the Property has undertaken any construction in the Well Restriction Area that has damaged or interfered with, or might damage or interfere with, any basal groundwater monitoring or extraction wells, or equipment associated with those wells.

Date:

July 12, 2016

Signature:



Printed Name:

D. L. Greenwood

Title:

PROPERTY MGR.

Property description:

**SECTION 2:**

All of that certain parcel of land situate at Honouliuli, District of Ewa, City and County of Honolulu, Island of Oahu, State of Hawaii, more particularly described as follows:

**Being the land described in deregistered Certificate of Title No. 975,762 recorded in the Bureau of Conveyances of the State of Hawaii as Document No. 2011-133200, described as LOT M-8-B (area 854.23 acres), as shown on Map 5, filed in the Office of the Assistant Registrar of the Land Court to the State of Hawaii with Land Court Application No. 1069 of the Trustees under the Will and of the Estate of James Campbell, Deceased, which lot has been deregistered from the Land Court System pursuant to Hawaii Revised Statutes Section 501-261.**

End of Property Description







**CERTIFICATION OF COMPLIANCE WITH DECLARATION OF  
ENVIRONMENTAL RESTRICTIONS (WELL RESTRICTION AREA)**

I am authorized to make this certification on behalf of the owner(s) of the property described below ("**Property**").

On behalf of said owner(s), I hereby certify, to the best of my and said owner(s)' information and belief, that the following is true and correct as of the date set forth below:

- No application for a water use permit to withdraw water from any well located or to be located in the area shown on the map attached hereto ("**Well Restriction Area**") has been filed by any owner, lessee, licensee, or other occupant or user of the Property (collectively "**Occupant**").

- No Occupant of the Property has undertaken any construction in the Well Restriction Area that has damaged or interfered with, or might damage or interfere with, any basal groundwater monitoring or extraction wells, or equipment associated with those wells.

Date:

July 26, 2016

Signature:

Steven Kai

Printed Name:

Steven Kai

Title:

Hawaii Plant Manager

Property description:

**SECTION 6:**

**PARCEL ONE:**

All of that certain parcel of land situate at Honouliuli, District of Ewa, City and County of Honolulu, Island of Oahu, State of Hawaii, more particularly described as follows:

**LOT M-9-A** (area 19.296 acres), as shown on Map 6, filed in the Office of the Assistant Registrar of the Land Court to the State of Hawaii with Land Court Application No. 1069 of the Trustees under the Will and of the Estate of James Campbell, Deceased.

**BEING** all of the land described in and covered by **Certificate of Title No. 921,358** issued to Syngenta Hawaii, LLC, a Hawaii limited liability company.

End of Parcel One Description



**PARCEL TWO:**

All of that certain parcel of land situate at Honouliuli, District of Ewa, City and County of Honolulu, Island of Oahu, State of Hawaii, more particularly described as follows:

**LOT 169** (area 0.693 acres), as shown on Map 27, filed in the Office of the Assistant Registrar of the Land Court to the State of Hawaii with Land Court Application No. 1069 of the Trustees under the Will and of the Estate of James Campbell, Deceased.

**BEING** all of the land described in and covered by **Certificate of Title No. 921,359** issued to Syngenta Hawaii, LLC, a Hawaii limited liability company.

End of Parcel Two Description

**PARCEL THREE:**


All of that certain parcel of land situate at Honouliuli, District of Ewa, City and County of Honolulu, Island of Oahu, State of Hawaii, more particularly described as follows:

**LOT 880** (area 93.117 acres), as shown on Map 109, filed in the Office of the Assistant Registrar of the Land Court to the State of Hawaii with Land Court Application No. 1069 of the Trustees under the Will and of the Estate of James Campbell, Deceased.

**BEING** all of the land described in and covered by **Certificate of Title No. 921,364** issued to Syngenta Hawaii, LLC, a Hawaii limited liability company.

End of Parcel Three Description







**CERTIFICATION OF COMPLIANCE WITH DECLARATION OF  
ENVIRONMENTAL RESTRICTIONS (WELL RESTRICTION AREA)**


I am authorized to make this certification on behalf of the owner(s) of the property described below ("**Property**").

On behalf of said owner(s), I hereby certify, to the best of my and said owner(s)' information and belief, that the following is true and correct as of the date set forth below:

- No application for a water use permit to withdraw water from any well located or to be located in the area shown on the map attached hereto ("**Well Restriction Area**") has been filed by any owner, lessee, licensee, or other occupant or user of the Property (collectively "**Occupant**").

- No Occupant of the Property has undertaken any construction in the Well Restriction Area that has damaged or interfered with, or might damage or interfere with, any basal groundwater monitoring or extraction wells, or equipment associated with those wells.

Date: July 27, 2016

Signature: 

Printed Name: Tim Law

Title: President

Property description:

**SECTION 8:**

**PARCEL ONE:**


All of that certain parcel of land situate at Honouliuli, District of Ewa, City and County of Honolulu, Island of Oahu, State of Hawaii, more particularly described as follows:

**LOT 882-A** (area 425.963 acres), as shown on Map 110, filed in the Office of the Assistant Registrar of the Land Court to the State of Hawaii with Land Court Application No. 1069 of the Trustees under the Will and of the Estate of James Campbell, Deceased.

**BEING** all of the land described in and covered by **Certificate of Title No. 1,062,206** issued to Fat Law's Farm, Inc., et al.

End of Parcel One Description







Arcadis U.S., Inc.

1003 Bishop Street

Suite 2000

Honolulu, Hawaii 96813

Tel 808 522 0321

Fax 808 522 0366

[www.arcadis.com](http://www.arcadis.com)

